JOB DESCRIPTION

JOB TITLE: CADCAM Programmer	**DEPARTMENT**: CAD Office
REPORTS TO: CAD Manager	**LOCATION:** H6 Stansted

JOB PURPOSE:

To produce 3 and 5 axis programs for 2D and 3D models.

MAIN RESPONSIBILITIES AND DUTIES:

- Produce 3 and 5 axis CNC programs with supporting documentation from both 2D drawings and 3D models
- Produce 3D model data from 2D drawings where model data is required but not available from the customer
- Plan and program machining methods for components
- Communicate with shop floor staff, management and customers to resolve engineering problems
- Assist with questions from shop floor staff and support ongoing live work
- Adhere to health and safety requirements
- Comply with quality and regulatory standards
- Perform any other duties within your capabilities as directed by the Company

Experience:

- Proven experience of Hypermill and Vericut
- Ability to read engineering drawings
- Good communication skills
- Ability to problem solve